



# MiX 4000

Internal Release Notes

Release Notes: 5.16.11

**POWERFLEET®**

## Contents

Fixes.....	3
Known issues.....	3

## Fixes

Description	Component	Version
Fixed a condition where the modem could unexpectedly reboot while attempting to activate a session during registration.	GSM	5.16.10
Fix how commissioning service determines if the IMSI matches one of the 8 commissioned APNs.	Commissioning	5.16.10
A fix has been added to ensure DTCO files are generated in the correct format so that downstream systems can process them reliably.	DTCO	5.16.11
Fixed panic button pressed for shorter than a second that could potentially be missed.	Inputs	5.16.11

## Known issues

Description	Severity
Version is not compatible with the EasyELD application.	