



# MiX 4000

Internal Release Notes

Release Notes: 5.16.12

POWERFLEET®

## Fixes

Description	Component	Version
Handle spontaneous modem reboots when trying to activate a PDP context	GSM	5.16.12
Enabled CAN auto retransmission to resolve intermittent RPM drops and inaccurate tachometer data observed in some OBDII scripts.	CAN	5.16.12
Tachometer and Config event alignment	Tachometer, Events	5.16.12

## Known issues

Description	Severity
Version is not compatible with the EasyELD application.	