



MiX 4000

Internal Release Notes

Release Notes: 5.10.27

POWERFLEET®

Hotfix

Description	Component	Version
Fixed repetitive device resets caused by excessive CAN bus load.	CAN	5.10.26
Fixed incorrect fuel consumption readings on legacy scripts by correcting CAN signal update logic.	CAN	5.10.26
Fixed the analog input filter to correctly detect brief or short-duration input signals.	Inputs	5.10.27
Improved EasyELD log transfer speed over Bluetooth to reduce sync time for drivers.	Bluetooth	5.10.27
Fixed a device lock-up issue that could prevent the unit from operating normally.	Core	5.10.27