



MiX 4000

Internal Release Notes

Release Notes: 5.10.29

POWERFLEET®

Hofix

Description	Component	Version
Fixed repetitive device resets caused by excessive CAN bus load.	CAN	5.10.26
Fixed incorrect fuel consumption readings on legacy scripts by correcting CAN signal update logic.	CAN	5.10.26
Fixed the analog input filter to correctly detect brief or short-duration input signals.	Inputs	5.10.27
Improved EasyELD log transfer speed over Bluetooth to reduce sync time for drivers.	Bluetooth	5.10.27
Fixed a device lock-up issue that could prevent the unit from operating normally.	Core	5.10.27
Recover from unexpected Bluetooth resets.	Bluetooth	5.10.28
Automatic Bluetooth re-enabling and reliability improvements.	Bluetooth	5.10.29
Recover from unresponsive legacy Bluetooth stack.	Bluetooth	5.10.29
IPv6 support.	Comms	5.10.29