



TELEMATICS
MOBILE INFORMATION EXCHANGE

Version 1: 21 April 2023



MiX4000
Release Notes

Fixes

Description	Component	Version
HOTFIX: Reverted speed filter changes which were causing erroneous harsh acceleration events.	Events	4.12.17

Known issues

Description	Severity
Comms delays on MiX 4000 seemingly resulting from bad network conditions.	High
Power loss (cold boot) mid-trip can lead to missing tacho for section prior to cold boot.	High
GPS TTFF improvement to address jumps from garages or tunnels. GPS Jumps when departing from garage.	Med