



TELEMATICS
MOBILE INFORMATION EXCHANGE

Version 1: 25 October 2022



MiX4000
Release Notes

Contents

Fixes	3
Known issues.....	3

Version 4.12.12 is a special version based on 4.12.9 with only one firmware change to address a critical issue (see fixes below).

Fixes

Description	Component	Version
A vulnerability has been addressed where if the unit went for extended periods without network coverage and its event storage became full, it could potentially get stuck in a startup sequence. Even though the chances are remote, the results are an unrecoverable failure and require unit swop-out.	Events	4.12.12

Known issues

ID (hyperlink)	Description	Severity
MIXT-7855	Comms delays on MiX 4000 seemingly resulting from bad network conditions.	High
MIXT-7567	Power loss (cold boot) mid-trip can lead to missing tacho for section prior to cold boot.	High
MX46-889	GPS TTFF improvement to address jumps from garages or tunnels	Med
SR-4905	GPS jumps when departing from garage.	
SR-9977	Iridium Satellites not communicating until firmware upload or OBC reset.	High